

FIG. 1




FIG. 2

3/16




FIG. 3




FIG. 4





FIG. 5




FIG. 6

5/16




FIG. 7

6/16






FIG. 8

INVENTOR: DUWAIN K. AKE

DOCKET: APAC-515

7/16



9
E/G.

8/16




FIG. 10

ATTY: FREDERICK H. GRIBBELL; PHONE: (513) 891-2100

278 — PHASE ERROR



10/16




FIG. 12

11/16







FIG. 13

12/16



INVENTOR: DUWAIN K. AKE

DOCKET: APAC-515

ATTY: FREDERICK H. GRIBBELL; PHONE: (513) 891-2100

13/16






FIG. 15



15/16



16/16




FIG. 18